

September 2012

EU2000iK1 GENERATORS

SAFETY AND EMISSIONS RECALL - STOP SALE/RENTAL NOTICE

Dear Honda Dealer Principal,

American Honda is announcing a Stop Sale Notice of certain EU2000iK1 generators. Any new or used units in dealer inventory must be inspected and, if necessary, repaired prior to sale.

Units within the affected serial number range may have an improperly positioned fuel tube clamp at the fuel tank outlet. The tabs of the improperly positioned fuel tube clamp could wear into an adjacent fuel tube causing a fuel leak.

Affected serial number range:

Model	Frame serial number:
EU2000iK1	EAAJ-2260273 ~ EAAJ-2485025

Campaign information:

- Inspect your inventory and confirm if you have any generators within the affected serial number range. If you identify in-stock units, follow the *Dealer Inventory Inspection* procedure on page 2.
- Units within the affected serial number range cannot be sold, or otherwise placed into service, until they have been inspected and if necessary repaired, as required by law. Any injury or damage which occurs from affected units sold after this Stop Sale Notice is the responsibility of the retailer.
- American Honda will be issuing a service bulletin shortly with inspection and repair procedures.
- New units in American Honda inventory within the affected serial number range that have a green sticker on the carton next to the bar code and have a black "DOT" located under the spark plug access panel, have their clamps properly positioned and are not part of this stop sale notice.

